





GENERAL SEMISOLIDO/VERTICALE M3

Line

POLYESTER

Function

FOR SLAB PLASTER-WORK IN AUTOMATIC AND NO

Materials

TRAVERTINE

How to use

For best results mix 2% to 3% of the catalyst with the adhesive; the paste formula make easy to measure. A homogeneous mixing will facilitate uniform catalysis. The catalysis rate is effected by temperature and by the proportion/quantity of catalyst. An excess of hardener/catalyst will increase the hardening speed, but weakens the adhesive seal.

Packaging

125ml-500ml-750ml

1-4lt

19lt

Characteristics

FOR MORE INFORMATIONS ASKING TECHNICAL DATA SHEET

Important

ALWAYS EFFECT A PRELIMINARY TEST BEFORE THE APPLICATION